

12	No Smoking Board	Not Displayed	COTPA Sec-4 Direction No Smoking area Smoking hear is an offence Board Should be written in English & Kannada both language Shall be Prominently displayed at inside the Entry/Exist of Each Floor.
13	Fire Siren	Not Installed	A fire Siren shall be installed in the premises to inform the inmates in case of a fire emergency/evacuate the area
14	Nominate one fire Nodal officer	-	A fire nodal officer shall be nominated either from teaching or no teaching staff.
15	Fire fighting training.	Not Imparted	At-least 40% of School Staff should be got trained in basic fire fighting at R.A.Mundkur fire & Emergency Services Academy, Bannerughatta road, Bangalore within 3 months or at an early date.

15) Fire Precautionary Measures:

- 1) Explosive and flammable materials should not be stored in the store room, UPS room, Electrical panel area, class rooms, laboratory and electrical cum panel premises.
- 2) Accumulation of combustible waste in and around the premises should be avoided.
- 3) The exit ways shall be always kept clear without any Obstruction.
- 4) Liquefied petroleum gas should not be stored in the building.
- 5) The doors shall not be kept locked / latched during working hours and shall be free from obstruction.
- 6) During the class hours the class room doors shall not be locked from inside to outside.
- 7) As per Honorable supreme court order all teachers and staffs shall be trained to handle safety equipment, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the fire safety day on 14th of every year by conducting fire safety drills with co-ordinate with fire service department.


Hence this "Fire Safety recommendation" is issued to "St. Joseph English Medium School-CBSE" Located at T.B.Dam Hosapete, Hosapete Taluk, Vijayanagar Dist. subject to strict adherence of the conditions as laid down in this Recommendations and to check the portable fire extinguisher & Hose reel hose, and to conduct drills periodically and the Management must not extend the height of the building beyond 15.0 meters. Subject to condition and compliance of the above recommendations in column-4 of serial-B within 3 months and compliance to undersigned.

The "Fire Safety recommendation" is valid for only one year from the date of issue and it is renewable.

Date- 18-03-2022.

Place- Ballari

Yours faithfully,


 ಇ. ಪ್ರವೀಣ್ ಅಗ್ನಿಶಾಮಕ ಅಧಿಕಾರಿ,
 ಕರ್ನಾಟಕ ರಾಜ್ಯ ಅಗ್ನಿಶಾಮಕ ಮತ್ತು
 ತುರ್ತು ಸೇವೆಗಳು,
 ಬಳ್ಳಾರಿ ವಲಯ, ಬಳ್ಳಾರಿ-04